

Work Order ID 53645



Page 1

November 11, 2009 1:35:47 PM

Item ID: D3136-041

Accept



Setup Start



Revision ID: E

Stop



Item Name: Window Assembly

Start Date: 11/12/09 Start Qty: 19.00



Cust Item ID:

Required Date: 11/12/09 Req'd Qty: 19.00

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Draw
Number

Draw
Rev.

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

D3136

Rev E

185

0.00



Small Fab

Memo

0.00

PULL FROM STOCK:

d3136-041 6 XB50285

3 XB46851

D3136-043 4 X B45168

6 X B48114

SCRAP/DESTROY PER NCR 09-099[1]

[Signature]

091111

190

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

09/11/12 *[Signature]*

W 09.11.11

Picklist Print

November 11, 2009 1:35:46 PM

Page 1

Work Order ID: 53645

Parent Item: D3136-041RevE

Parent Item Name: Window Assembly

Comments:

Start Date: 11/12/09

Required Date: 11/12/09

Start Qty: 19.00

Required Qty: 19.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3136-041RevE		Manufactured	No				Each	10.0000	9.0000			

Window Assembly

Warehouse Loc Qty Loc Code

Location

Main Warehouse

ST

10

46851

3

50285

6

53477

1

D3136-043RevE

Manufactured

No



Window Assembly

Each

10.0000

10.0000



Warehouse Loc Qty Loc Code

Location

Main Warehouse

ST

10

45168

4

48114

6

h

h